

Scan Victory	XTO Energy	Weldon Cox 3H	Spudded: 5/13/12	David Kelly	Nickey Reynolds
281-605-2120	N 31 24 29 W 96 12 37			Limestone Co.	
From Jewett, TX take Hwy 39 north for about 7.4 miles to Wilson Chapel Cemetary Road. Turn right and go about 3/10 of a mile and turn right into mine entrance. Go about 8/10 of a mile to Main Haul Road. Turn right and go about 1/10 of a mile and turn left onto second road. Go about 1 mile and turn right onto Fullen 4-H lease road. Follow to new location behind existing well.					
Scan Discoverer	XTO Energy	Red Raider 1	Spudded: 3/14/12	Tommie Cottrell	Dewayne Harris
281-605-2121	N 31 39 2 W 94 12 26			Shelby Co.	
From Loop 500 in Center, TX, go south on Hwy 96 for about 7 miles. Turn right on CR 1017 and go about 3/10 of a mile and turn right back on CR 1017. Go about 3 2/10 of a mile to location on right.					
Scan Energy	Midstates Petroleum Corp.	Perkins 34-2	Spudded: 5/14/12	Austin Ralph	Alan Nichols
281-605-2122	N 30 45 25 W 92 28 4			Evangeline Parish	
From Pine Priairie, LA, on Hwy 13 go about 2 miles south to Ambrose Road. Turn right (will have Midstate Sign) and go about 2.4 miles on Ambrose Road to Lease road on right. Turn right and go about 1/2 of a mile to lease road on left. Stay on road to location.					
Scan Pride	Midstates Petroleum Corp.	A & H Farms 7H 1	Spudded: 4/13/12	James Blankinship	Ray Dalton
281-605-2123	N 30 28 29 W 93 13 51	Rigging down 5/18/12		Beauregard Parish	
From either Houston or Lafayette, go to Exit # 33 (Hwy 171) on Interstate 10 and proceed north for about 18.5 miles. Location is off Hwy 171 on the east side of Hwy. If coming south on Hwy 171, go about 2 miles south of the Ragley overpass to location on the east side of hwy. Next Loc: From A & H Farms 7H-1 travel north on US 171 for about 2 miles. Turn east on US 190 and go about 26 miles to Eunice, LA. Turn left on LA 13 north and go about 10 miles to Mamou, LA. Turn right on LA 160 east. AT intersection of LA 160 and LA 1104 go east on LA 104 for about 2 miles. Turn left on Tiger Lane. Board road on location on left. (Dougja #1)					
Scan Explorer	XTO Energy	RCFU 480	Spudded: 5/13/12	Kent Allison	Charles Nichols
281-605-2124	N 32 53 40 W 102 53 39			Gaines Co.	
From Seminole Go west on 62/180 for about 9 miles to FM 1757. Turn right and go about 14.6 miles and turn right on lease road. Go about 2.1 miles and turn left. Go about 8/10 of a mile and turn left. Go about 3.10 of a mile and location is on left.					
Scan Scout	XTO Energy	Cosson 25	Spudded:	James Phillips	Kenny Fickey
281-605-2125	N 31 36 12 W 96 13 5	Rigging up 5/18/12		Freestone Co.	
From Dew, TX at I-45 and Hwy 179 towards Teague for about 3.8 miles to CR 711. Turn left on CR 711 and go about 4/10 of a mile and turn right on CR 711. Go about 7/10 of a mile to location on left.					
Scan Producer	SM Energy	Horizon Properties 1-H	Spudded: 4/9/12	Shawn Mills	Chad Paul
281-605-2126	N 30 48 44 W 95 20 2			Walker Co.	
From the intersection of Hwy 19 and FM 980 in Riverside, TX, travel east on FM 980 for about 5.3 miles. Turn right on Old Staley road (Note: Old Staley Road is about 300' Prior to entering San Jacinto City). Go about 1/10 of a mile and bear right on lease road where old Staley Road makes a left turn. Follow about 1.2 miles to location.					
Scan Traveler	SM Energy	Rebecca 807-H	Spudded: 4/23/12	John Dumolt	Travis Smith
281-605-2127	N 32 48 20 W 101 32 11			Borden Co.	
From Gail, TX go west on Hwy 180 for about 4.1 miles. Turn right on lease road and go north on lease road about 4.1 miles through 3 cattle guards. Go to cross road and turn left and go west about 1.1 miles. Turn left through cattle guard and go about 4/10 of a mile to location. (KEEP GATES CLOSED AND LOCKED. COMBO 4425)					
Scan Spirit	Anadarko Petroleum	J R Kyle "A" 53 HH	Spudded: 3/15/12	Keith Davis	Allen Blackwell
281-605-2129	N 32 5 25 W 94 17 6			Panola Co.	
From Carthage loop take Hwy 59 south for about 2 miles and turn left on FM 2517. Go about 2.4 miles and turn right on CR 405. Go about 1.1 miles and turn right on lease road. Go about 200 feet to rig. Next Loc: From Loop in Carthage, take Hwy 59 south for about 2.2 miles. Turn left on FM 2517 and go about 2.1 miles. Turn right on CR 405 and go about 1.1 miles to lease road on right. Turn right and go about 200 yards and rig is on the					
Scan Cross	XTO Energy	J A Gilliam 2-28	Spudded: 5/6/12	Donald Seahorn	Hershel West
281-605-2130	N 31 32 2 W 96 18 29			Limestone Co.	
From the intersection of Hwy 164 and FM 80 in Donie, TX, take Hwy 164 west for about 4.9 miles and turn right on FM 489. Go about 7/10 of a mile and turn left on CR 811. Go about 1.5 miles to 4 way intersection and go straight for about 3/10 of a mile. Turn right on lease road and go about 2/10 of a mile to location. Next Loc: From the intersection of FM 489 west and FM 80 @ Freestone, take FM 80 south and go about 1 mile. Turn left on CR 750 and cross railroad tracks. Go about 2/10 of a mile and turn right on CR 750. Go about 1/10 of a mile and cross cattle guard. Go about 1/10 of a mile to "Y" stay right. Follow lease road for about 2/10 of a mile to "Y" stay left. Go about 2/10 of a mile and turn left and follow lease road to location. (TH McWatters #36)					
Scan Gold	XTO Energy	River Cats 1-H	Spudded: 5/11/12	Jack Hodge	Jeff Webster
281-605-2131	N 31 3 42 W 96 29 13			Robertson Co.	
From the light in Franklin, TX, take Hwy 46 north for about 1.2 miles to Old Boon Prairie Road. Turn right and go about 1/5 a mile to county road. Turn right and go about 3/10 of a mile to lease road. Turn right and follow to location.					
Scan Freedom	XTO Energy	Threshers 1H	Spudded: 5/7/12	Wise Menah	Joey Dover
281-605-2132	N 31 1 59 W 96 30 48			Robertson Co.	
From Franklin, TX at intersection of Hwy 79 and Hwy 46 take Hwy 46 north for about 4.8 miles. Turn left on FM 979 and go about 1.1 miles to Little Mississippi Cemetary Road. Turn left and go about 3.4 miles and turn right on Handcock lease road. Go about 2/10 of a mile and bear left to location.					
Scan Texas	XTO Energy	Fullen 11 H	Spudded: 4/13/12	Albert Bender	Kelly Dodd
281-605-2133	N 31 25 12 W 96 12 7			Freestone Co.	
From Jewett, TX take Hwy 39 north for about 7 miles. Turn right on Wilson Chapel Cemetary Road and go about 3/10 of a mile. Turn right to gate guard (MUST HAVE MINE CARD). Go about 3.10 of a mile to first stop sign and turn right. Go about 3/10 of a mile to main haul road and turn left. Go about 5/10 of a mile and turn on the first right. Go about 1.4 miles and turn right to location.					
Scan Patriot	Devon Energy	TJT Minerals 1H	Spudded: 4/5/12	Timmy Owens	Cedric Alexander
281-605-2134	N 32 31 36 W 94 40 9			Harrison Co.	
From junction of Hwy 59 and Hwy 43 north of Marshall, TX, take Hwy 43 north for about 11 miles. Turn right on CR 2682 and go about 1 mile. Turn left on lease road and follow to location.					
Scan Liberty	Samson	Frost Lumber GU 1 #3H	Spudded: 4/13/12	Mitchel Clemens	James Manderud
281-605-2135	N 32 4 42 W 94 9 17			Panola Co.	
From the intersection of 31 and 2517 in Panola County, go south on 31 for about 3.2 miles. Turn right on CR 449 and go about 8/10 of a mile. Turn right on lease road and go about 6/10 of a mile. Turn right on lease road and go about 1.1 miles to new lease road. Veer left for about 600' to location.					
Scan Star	Samson	Mildred 2H	Spudded: 5/6/12	Horace Clifton	Jeremy Dickens
281-605-2136	N 31 45 52 W 93 51 56			Shelby Co.	
At the intersection of Hwy 87 and Loop 500 in Center, TX go south on Hwy 87 for about 5.2 miles. In Shelbyville take a left and go est on Hwy 417. Go about 1.2 mile to a fork in the road. Take the fork to the right on FM 2694. Go about 9.2 miles to where the road "T". Take a right on FM 2694 and go about 1/10 of a mile to where the road forks. Stay left on FM 2694 and go about 2.4 miles to the intersection in Huxley. Turn left onto FM 3172 and go north about 1/4 of a mile. Turn right onto lease road and travel east for about 500' to location.					
Scan Glory	Navidad Resources, Inc.	Marty Hyde #2	Spudded: 5/12/12	Jaylon Bolton	Reggie Murray
281-605-2137	N 31 0 40 W 95 37 5			Houston Co.	
From Crockett, TX take Hwy 19 to Lovelady. Go about 15 miles to Lovelady and turn right on 1280. Cross Railroad tracks and take a left on Hwy 230. Go about 11 miles through Weldon and turn right on 3510. Follow 3510 to Eastham Guard gate. Stay straight and cross two cattle guards. Take a right behind barn and follow for about 1.2 mile to location.					
Scan Eagle	Cimarex Energy	Tres Equis State 5	Spudded: 4/26/12	Bib Register	Chuck High
281-605-2138	N 32 15 10 W 103 36 34			Lea Co.	
From Jal, New Mexico, go west on Hwy 128 for about 27 miles to mile marker 27. Turn north and go about 4 miles. At the "Y" hold right and go about 2 miles to location road.					
Scan Endeavor	Anadarko Petroleum	CGU 10-53 HH	Spudded: 4/4/12	David Blankinship	Michael Thornton
281-605-2139	N 32 11 17 W 94 21 21	Rigging down & moving 5/18/12		Panola Co.	
From loop in Carthage, take CR 201 north and go about 7/10 of a mile. Turn right on lease road. From Loop in Carthage, take Hwy 79 south for about 3 miles and turn right on FM 959. Go about 1.7 miles and turn right on lease road. Go about 3/10 of a mile and turn right. Go about 3/10 of a mile and turn right and go about 600' to location. (CGU 23-52HH)					

