Kenny Fickey

Tony Rangel

Spudded: 6/15/25



SABINE

(P) Bonner A CV 2H

Scan Victory

Jean Victory	S/IBINE (I)	Donner // CV ZII	<u> </u>	Tony Ranger	Remity Fickey
430-562-8462		Norseman I Sheries- 1500 HP SCR		HARRISON, CO.	(Ark-La-Tex)
		shall and Longview Tx. Travel West on the South			or North on
FM 968 go .5 miles. Turn left or North onto Muntz Cut Off Rd. Drive .26 miles and turn left onto the lease road. <b>NEXT RIG MOVE</b> :					
Scan Discoverer 281-746-9653		ODESSA YARD	<mark>Spudded</mark> :		(Pormion Posin)
281-746-9653   Norseman I Series- 1500 HP SCR   (Permian Basin)  From Odessa: Go west on I20 to exit 104 (FM 866 Goldsmith HWY) go North on 866 for 2 miles. 551 South FM 866, Odessa, TX 79763 NEXT RIG MOVE:					
		H12C Mullins AN 2HH		Paxton Lindsey	Inocente Cobio
Scan Pride 903-508-5706	` '	Norseman II Series- 2000 HP AC	Spudded: 8/3/25	Paxton Lindsey PANOLA, CO.	(Ark-La-Tex)
			1186 0.5 miles. Turn	· ·	·
From DeBerry, TX intersection FM 31 & US-79, head Southwest on US-79 4.6 miles. Turn right on FM 1186 0.5 miles. Turn left on lease road and follow to location.  NEXT RIG MOVE:					
Scan Spirit	SABINE (P)	Stewart A 1H	<mark>Spudded</mark> : 7/30/25	<mark>Shawn Baird</mark>	Eric Blake
281-606-2279	<u>I</u>	Norseman I Series- 1500 HP SCR		UPSHUR, CO.	(Ark-La-Tex)
From the intersection of hwy 135 and hwy 64 in arp tx go NW on hwy 64 4.2 miles, turn south on county road 230 or "swinney road" go 1.37 miles and turn right or west onto lease road, go .42 miles down lease road and turn right into the location. <b>NEXT RIG MOVE</b> :					
Scan Cross	Tischer Energy <b>(P)</b>		<mark>Spudded</mark> : 7/19/25	Michael Bacon	Dustin Smith
903-204-4209		Norseman I Series- 1500 HP SCR		RUSK, CO.	(Ark-La-Tex)
From the intersection o	f US 80 and US 271 in Gladewat	er TX head west on us 80 towards big sandy for	5.8 miles to lease road	on left and follow to	o rig. On lease road
you will cross over railroad tracks as soon as you turn off US 80 (PROCEED WITH CAUTION 15 MPH SPEED LIMIT) If we shut down the railroad it is \$2500/hour. Also					
the lease road is narrow and has steep edges. NEXT RIG MOVE: From Brady, Arkansas, turn left onto AR-29 N and follow it 6.3 miles to AR-360 E. Turn right onto					
AR-360 E (Homan RD) and follow 6.7 miles to AR-53 N. Turn left onto AR-53 N and follow for 3.8 miles, then turn right to stay on AR-53 N follow for 2.4 miles to Lafayette County Road 81. Turn right on Lafayette County Road 81 and follow it 1.8 miles to Lafayette County Road 21. Turn right onto Lafayette County Road 21 and					
	road on left. Turn left on lease				
Scan Patriot		ODESSA YARD	Spudded:		
903-205-8399		Norseman I Series- 1500 HP SCR			(Permian Basin)
@ ODESSA YARD. <b>NEX</b> T	FRIG MOVE:				
Scan Liberty		Payne Deep Bounds 1H	Spudded: 6/22/25	Jon Bruce Trotter	Adam Diaz
281-766-4976 From the intersection N	1	Norseman II Series- 2000 HP AC go NE on Hwy 79 for 11 miles, turn right on CR	3150 go 0 37 miles to	PANOLA, CO.	(Ark-La-Tex)
		.75 miles and turn right on lease road, go 0.11 n			
From the intersection NE loop and Hwy 79 in Carthage, go NE on Hwy 79 for 6miles, turn right on FM 123, go 5.6 miles to CR 323 and turn right, go 1.6 miles and turn left on Private Road 7231. Follow Private Road 7231 for 0.7 miles and stay left to enter the location.					
		· I		lana D	Lab O "
Scan Vision	Continental Resources (MDT)		<mark>Spudded:</mark> 07/01/25	Lance Dement	John Carroll
281- 397-3747	ako ovit 101. Hoad south on EM	Norseman II Series- 1500 HP AC	Land EM 1222 Turn ri	WINKLER, CO.	(Permian Basin)
From I20 in PennWell take exit 101. Head south on FM 1601 for 15 miles to the intersection of FM 1601 and FM 1233. Turn right (west) on FM 1233 and go 2.6 miles. Turn left (south) into cattle guard. Travel lease road for 1.6 miles to location. <b>NEXT RIG MOVE:</b> GRANT SMITH TRUCKING. 38 MILE MOVE. Take exit 118 (South					
Grandview Ave) onto East Pool road. Follow E Pool Road for 1.8 miles (road turns into FM 3503) turn left at the ORREX sign and immediately turn left onto lease road.					
Follow lease road for 0.1 mile into location.					
Scan Quest	Conoco Phillips (P)	Windward Federal 705H	<mark>Spudded:</mark> 8/17/25	<mark>Josh Miller</mark>	Randy Gay
281-766-7242		Norseman II Series- 2000 HP AC		LEA, CO. (Perm	ian Basin) (NM)
From the major intersection of Hwy 128 and Hwy 18 in Jal Nm. Travel west on Hwy. 128 for 33 miles. Turn left and travel southwest on Buck Jackson Rd. for 0.4					
miles, turn left and travel south for 2.5 miles, turn left and go east for 0.1 miles to wellsite on the right. <b>NEXT RIG MOVE:</b>					
Scan Titan			<mark>Spudded</mark> :		
903-650-8486		Norseman II Series- 2000 HP AC			(Permian Basin)
NEXT RIG MOVE:	Aethon (P)	ANKY-ALCO HAY B 4HB	Spudded: 7/22/25	Dewayne Harris	Chad McKinney
Scan Legacy 281-606-0182		Norseman II Series- 2000 HP AC	<mark>5paudeu.</mark> 1/22/23	ANGELINA, CO.	(LA) (Ark-La-Tex)
		ease rd. entrance on the right. NEXT RIG MOVE:			( // ( · · · · · · · · · · · · · · · · · ·
Scan Explorer		Linsey 1H	Spudded: 6/28/25	Andrew Crump	Armando Garcia
432-614-6424	(MDI)	Norseman II Series- 2000 HP AC	<del>opudaca.</del> 0/20/23	LEON, CO.	(Ark-La-Tex)
From Hwy 75 & Hwy 79		EAST on Hwy 79 to CR 218. Turn Left on CR 218		left go 0.3 miles to lo	ocation. <b>NEXT RIG</b>
MOVE: From the intersection of interstate 45 and hwy 79, take hwy 79 north and travel 12.0 miles. Turn right on CR 224. Go 0.7 miles. Turn left CR 2612 and go 1.1 miles. Turn right on lease road and go 0.7 miles to location.					
illiles. Turn right on leas	<u>-</u>	<u> </u>			
Scan Reliant	Continental Resources (MDT)		<mark>Spudded:</mark> 7/17/25	Dustin Gilbert	Brad Miller
281-962-4136 FROM 120 IN PYOTE GO		Norseman II Series- 2000 HP AC	N 1776 GO 7 7 MILES A	WINKLER, CO	(Permian Basin)
FROM 120 IN PYOTE GO SOUTH ON 1927 FOR 15 MILES UNTIL T OF 1927 & 1776 TURN WEST /RIGHT ON 1776 GO 7.7 MILES AND ENTRANCE TO LEASE ROAD IS ON THE NORTH/ RIGHT SIDE OF ROAD, FOLLOW RIG SIGNS. NEXT RIG MOVE:					
Scan Denali	E OF ROAD , FOLLOW RIG SIGNS	. NEXT RIG MOVE:			
Scall Deliali	E OF ROAD , FOLLOW RIG SIGNS  Continental Resources (MDT)		Spudded: 8/15/25	Truitt Thompson	Justin Molandes
	Continental Resources (MDT)	UTL Wyatt Earp 2221A Norseman II Series- 2000 HP AC		PECOS, CO.	(Permian Basin)
From Pyote: I-20 West	Continental Resources (MDT) exit 66 in Pyote and travel Nortl	UTL Wyatt Earp 2221A	and travel 4.2 mile. Tu	PECOS, CO. urn left onto Lease R	(Permian Basin)
From Pyote: I-20 West miles and turn LEFT. Tra	Continental Resources (MDT) exit 66 in Pyote and travel Nortl	UTL Wyatt Earp 2221A  Norseman II Series- 2000 HP AC  n on TX-115 for .3 miles. Turn left onto FM 2355	and travel 4.2 mile. Tu	PECOS, CO. urn left onto Lease R NEXT RIG MOVE:	(Permian Basin)
From Pyote: I-20 West miles and turn LEFT. Tra Tyler Yard: (903) 597-5	Continental Resources (MDT) exit 66 in Pyote and travel Nortl exel .9 miles and turn right. Trav	UTL Wyatt Earp 2221A  Norseman II Series- 2000 HP AC  n on TX-115 for .3 miles. Turn left onto FM 2355	and travel 4.2 mile. Tu d travel into location.	PECOS, CO.  urn left onto Lease Ro  NEXT RIG MOVE:  Rig Manager on co	(Permian Basin) oad and travel .6 duty is Highlighted